

JOBY® gorillatorch FLARE™


Warnings: Do not look directly into light. Do not submerge the Gorillatorch in liquid. Please do not store flashlight in conditions below 0°F (-17.8°C) or exceeding 100°F (37.7°C). Extended exposure to extreme temperatures could cause material degradation. Keep magnetic feet away from digital storage devices.

Danger: Incorrect battery orientation may cause explosions and burns!

Support: <http://www.joby.com/support>

Please use this product responsibly: Joby is not liable for consequences, direct or indirect, resulting from the use of this product.

Inserting
the batteries
(3 AA only)



$\leq 1/2$
sec

Tap  button to
turn power on



1
sec

Press
and hold  button to
turn power off



$\leq 1/2$
sec

Ta  button to
cycle through
settings

